# Construction Updates



March 2024

## **Building B2**



Activity	B2
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	100%
Flat Flooring	100%
Flat Electrical Wiring	99%
Internal Painting	99%
Door Shutter	100%
Window	100%
False Ceiling	100%
СР	95%
Window Subframe	100%
External Paint	100%

#### **Building B3**



Activity	В3
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	100%
Flat Flooring	100%
Flat Electrical Wiring	99%
Internal Painting	99%
Door Shutter	100%
Window	100%
False Ceiling	100%
СР	95%
Window Subframe	100%
External Paint	100%

#### **Building D1**




Activity	D1
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	100%
Flat Flooring	100%
Flat Electrical Wiring	98%
Internal Painting	50%
Door Shutter	100%
Window	100%
False Ceiling	95%
СР	80%
Window Subframe	100%
External Paint	98%

#### **Building D2**




Activity	D2
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	100%
Flat Flooring	100%
Flat Electrical Wiring	99%
Internal Painting	60%
Door Shutter	100%
Window	100%
False Ceiling	100%
СР	85%
Window Subframe	100%
External Paint	100%



Activity	<b>C5</b>
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	100%
Flat Flooring	100%
Flat Electrical Wiring	90%
Internal Painting	35%
Door Shutter	98%
Window	98%
False Ceiling	98%
СР	0%
Window Subframe	100%
<b>External Paint</b>	75%




Activity	<b>C1</b>
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	90%
Flat Flooring	30%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	5%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	0%



Activity	C2
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	99%
Waterproofing	100%
Fabrication	100%
Gypsum	90%
Flat Flooring	18%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	0%




Activity	С3
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	100%
Flat Flooring	48%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	5%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	2%



Activity	<b>C4</b>
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	100%
Fabrication	100%
Gypsum	95%
Flat Flooring	78%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	55%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	60%

#### **Building D3**



Activity	D3
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	99%
Waterproofing	70%
Fabrication	95%
Gypsum	85%
Flat Flooring	35%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	5%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	0%



Activity	G6
RCC	100%
Blockwork	100%
Wall Conduit	77%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	82%
Waterproofing	88%
Fabrication	100%
Gypsum	75%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	80%
External Paint	0%



Activity	J2
RCC	100%
Blockwork	90%
Wall Conduit	86%
Toilet & Kitchen Back coat	86%
Conceal Plumbing	86%
Waterproofing	68%
Fabrication	100%
Gypsum	37%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	86%
External Paint	0%




Activity	J3
RCC	100%
Blockwork	90%
Wall Conduit	79%
Toilet & Kitchen Back coat	88%
Conceal Plumbing	88%
Waterproofing	50%
Fabrication	100%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	79%
External Paint	0%




Activity	J4
RCC	100%
Blockwork	100%
Wall Conduit	75%
Toilet & Kitchen Back coat	97%
Conceal Plumbing	56%
Waterproofing	0%
Fabrication	100%
Gypsum	75%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	95%
External Paint	0%

## **Building A4**



Activity	A4
RCC	100%
Blockwork	80%
Wall Conduit	79%
Toilet & Kitchen Back coat	79%
Conceal Plumbing	79%
Waterproofing	79%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	79%
External Paint	0%



Activity	C6
RCC	100%
Blockwork	95%
Wall Conduit	88%
Toilet & Kitchen Back coat	80%
Conceal Plumbing	100%
Waterproofing	60%
Fabrication	100%
Gypsum	13%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	0%

#### **Building E2**




Activity	<b>E2</b>
RCC	100%
Blockwork	100%
Wall Conduit	100%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	83%
Fabrication	100%
Gypsum	98%
Flat Flooring	10%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
<b>External Paint</b>	0%



Activity	G2
RCC	100%
Blockwork	90%
Wall Conduit	50%
Toilet & Kitchen Back coat	68%
Conceal Plumbing	75%
Waterproofing	18%
Fabrication	0%
Gypsum	35%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	88%
<b>External Paint</b>	0%




Activity	J5
RCC	100%
Blockwork	90%
Wall Conduit	6%
Toilet & Kitchen Back coat	77%
Conceal Plumbing	55%
Waterproofing	0%
Fabrication	100%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
External Paint	0%




Activity	J6
RCC	100%
Blockwork	90%
Wall Conduit	88%
Toilet & Kitchen Back coat	88%
Conceal Plumbing	75%
Waterproofing	63%
Fabrication	0%
Gypsum	70%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	44%
<b>External Paint</b>	0%

#### **Building D4**




Activity	D4
RCC	100%
Blockwork	85%
Wall Conduit	79%
Toilet & Kitchen Back coat	54%
Conceal Plumbing	85%
Waterproofing	0%
Fabrication	100%
Gypsum	13%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	12%
External Paint	0%

## **Building A2**




Activity	A2
RCC	60%
Blockwork	0%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
External Paint	0%

## **Building B1**




Activity	B1
RCC	100%
Blockwork	100%
Wall Conduit	97%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	100%
Waterproofing	75%
Fabrication	100%
Gypsum	95%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
External Paint	0%




Activity	С9
RCC	100%
Blockwork	80%
Wall Conduit	0%
Toilet & Kitchen Back coat	80%
Conceal Plumbing	61%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
External Paint	0%

#### **Building E1**




Activity	E1
RCC	100%
Blockwork	80%
Wall Conduit	71%
Toilet & Kitchen Back coat	36%
Conceal Plumbing	36%
Waterproofing	0%
Fabrication	0%
Gypsum	6%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	47%
External Paint	0%




Activity	J7
RCC	10%
Blockwork	0%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
<b>External Paint</b>	0%




Activity	F2
RCC	100%
Blockwork	25%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
<b>External Paint</b>	0%



Activity	F3
RCC	100%
Blockwork	28%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
External Paint	0%



Activity	F4
RCC	60%
Blockwork	12%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
<b>External Paint</b>	0%



Activity	F5
RCC	76%
Blockwork	32%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
External Paint	0%




Activity	G3
RCC	100%
Blockwork	74%
Wall Conduit	0%
Toilet & Kitchen Back coat	25%
Conceal Plumbing	42%
Waterproofing	0%
Fabrication	80%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	38%
<b>External Paint</b>	0%




Activity	G4
RCC	100%
Blockwork	35%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	23%
Waterproofing	0%
Fabrication	80%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	100%
External Paint	0%



Activity	G5
RCC	100%
Blockwork	100%
Wall Conduit	88%
Toilet & Kitchen Back coat	100%
Conceal Plumbing	81%
Waterproofing	88%
Fabrication	100%
Gypsum	50%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	80%
<b>External Paint</b>	0%



Activity	<b>G7</b>
RCC	10%
Blockwork	0%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
<b>External Paint</b>	0%



Activity	J1
RCC	5%
Blockwork	0%
Wall Conduit	0%
Toilet & Kitchen Back coat	0%
Conceal Plumbing	0%
Waterproofing	0%
Fabrication	0%
Gypsum	0%
Flat Flooring	0%
Flat Electrical Wiring	0%
Internal Painting	0%
Door Shutter	0%
Window	0%
False Ceiling	0%
СР	0%
Window Subframe	0%
<b>External Paint</b>	0%





For more updates do visit us at www.xrbia.com